Download 2nz Fe Engine Diagram

The created situation is that the MAF sensor gets less “sensitive” and detects less air than it is actually entering the engine. The reaction of the ECM computer ...??????????????